## City of Kyle - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping \*purposes:

City of Kyle 1050002 520 E RR 150 **Contact Name:** Mickal Morrison Kyle, Texas 78640 Phone Number: 737-877-2927

**BPAT Information** 

**Company Name:** Safewater Backflow and Irrigation

**Brad Weyant Tester Name:** Address: 609 E 50TH

AUSTIN, Texas 78751

Phone Number: 5126059790

**Email Address:** brad@safewateratx.com

License Number: BP0016935 License Expiration: 12/3/2024

**Contact Information** 

**Property Type:** Residential

**Business Name: Property Address:** 

363 Jackson River Loop

Kyle, TX 78640

**Company Name:** Contact Name:

**Mailing Address:** 363 Jackson River Loop

Kyle, TX 78640

**Date Tested for Accuracy:** 

3/14/2024

Phone Number:

**Email Address:** 

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

**Backflow Method: Double Check Valve** 

Main Assembly Manufacturer: Apollo Model: DC4A Size: 1 Serial Number: 01551D

Location: Left side of driveway 10 feet from meter

Hazard Type \*\*\*\*: Irrigation - Non Chemical

**Test Result:** Passed New Installation Reason for Test:

Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes

Is the assembly installed on a non-potable water supply (auxiliary)? No

Differential pressure

gauge used:

MidWest 845-5 (potable) Serial Number: 09231317

	Double Check Valve	
	Check Valve #1	Check Valve #2
Initial Test	Held at 1.9 PSID	Held at 2 PSID
Date: 10/8/2024	✓ ClosedTight	✓ ClosedTight
Time: 10:55 AM	Leaked	Leaked
Repairs and Materials Used		
Repair Details		
Test After Repairs	Held at 0 PSID	Held at 0 PSID
	Closed Tight	Closed Tight

Remarks

The above is certified to be true at the time of testing.

\* TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC 290.46(B)]

\*\* USE ONLY MANUFACTURER'S REPLACEMENT PARTS

\*\*\*\* Indicates additional information not present on the standard TCEQ report