

4050 FM 1660 Hutto, Texas 78634 2983 512-759-1286 Fax 512-759-

	IN LOVE INCLUDING	ON ASSEMBLY T	EST AND MA	AINTEN	ANCE REPO	ORT		
PWS I.D: <b>2460022</b> MAILING ADDRESS	_408 Doodle Hutto, TX 786	534						
	Taylor Morrison							
	/ICE 408 Doodle Hutto,							
	_7/16/2024_2:15PM							
-						_		
	tion assembly detailed batting within acceptable		ed and maintain	ed as rec	quired by TCE0	Q regula	ations and	
		TYPE OF A	ASSEMBLY					
() Reduced Pressure ZONE			() Reduced Pressure Principle-Detector					
(X) Double Check Valve			() Double Check-Detector					
() Pressure Vacuum Breaker			() Spill-Res	sistant Pr	essure Vacuu	m Break	cer	
Manufacture	er: Apollo							
Model # DC	4A	Serial # 82800	)C					
Location of	device Right front yard	5 feet from meter						
Is the assembly instal	lled in accordance with I			d/or local	codes? Yes_			
	Reduced Pressure Principle Assembly				Pressure Vacuum Breaker			
	Double Check Valve	e Assembly	Relief Valve		Air Inlet		Check Valve	
	1st Check	2nd Check			Opened at	psid	Held at	psid
Initial Test	1st Check Held at 2.2 Psi	2nd Check Held at 2.2 psid	Opened at	psid	Opened at Did not Open	psid	Held at Leaked	psid
Initial Test	Held at 2.2	Held at 2.2 psid	Opened at  Did not open	psid		-		
Initial Test  Repairs and Materials Used	Held at 2.2 Psi  Closed Tight X Leaked	Held at 2.2 psid  Closed Tight X Leaked	Did not open	•		-		
Repairs and	Held at 2.2 Psi  Closed Tight X Leaked	Held at 2.2 psid  Closed Tight X Leaked		•		-		
Repairs and Materials Used	Held at 2.2 Psi  Closed Tight X Leaked □	Held at 2.2 psid  Closed Tight X Leaked   Held at psid	Did not open		Did not Open		Leaked	
Repairs and Materials Used  Test After  Repair	Held at 2.2 Psi  Closed Tight X Leaked □	Held at 2.2 psid  Closed Tight X Leaked   Held at psid Closed Tight	Did not open		Did not Open		Leaked	
Repairs and Materials Used  Test After  Repair  The above is certification.	Held at 2.2 Psi  Closed Tight X Leaked   Held at psid Closed Tight   Closed Tight	Held at 2.2 psid  Closed Tight X Leaked   Held at psid Closed Tight □	Did not open Opened at	psid	Did not Open	psid	Leaked	
Repairs and Materials Used  Test After  Repair  The above is certification.	Held at 2.2 Psi  Closed Tight X Leaked   Held at psid Closed Tight   ded to be true at the time lake / Model Mid West	Held at 2.2 psid  Closed Tight X Leaked   Held at psid Closed Tight □	Did not open Opened at	psid Calibrat	Opened at	psid	Leaked	

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS \*\* USE ONLY MANUFACTURER'S REPLACEMENT PARTS

Firm Phone # 512-605-9790