

4050 FM 1660 Hutto, Texas 78634 2983 512-759-1286 Fax 512-759-

BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

CONTACT PERSON LOCATION OF SERVINSPECTION DATE The backflow prevent	_411 Doodle Ln Hutto, TX Taylor Morrison /ICE 411 Doodle Ln. Hut _7/1/2024_11:30AM tion assembly detailed be ating within acceptable	tto, TX 78634elow has been teste			itions and	
		TYPE OF A	ASSEMBLY			
() Reduc	ed Pressure ZONE		() Reduced Pressure Principle-Detector			
(X) Double Check Valve			() Double Check-Detector			
() Pressure Vacuum Breaker			() Spill-Resistant Pressure Vacuum Breaker			
Manufacture	er: Apollo					
Model # DC4A Serial #			.C			
Location of	device Right front yard 5	5 feet from meter				
Is the assembly instal	led in accordance with n	nanufacturer recomr	mendations and/or loca	I codes? Yes		
	Reduced F	Pressure Principle As	ssembly	Pressure Vac	uum Breake	r
	Double Check Valve Assembly		Relief Valve	Air Inlet Check Valve		/alve
	1st Check	2nd Check		Opened at psid	Held at	psid
Initial Test	Held at 2.2 Psi	Held at 1.7 psid	Opened at psid	Did not Open	Leaked	
	Closed Tight X Leaked □	Closed Tight X Leaked □	Did not open			
Repairs and Materials Used						
Test After	Held at psid Closed Tight □	Held at psid Closed Tight □	Opened at psid	Opened at psid	Held At	psid
Repair						
The above is certific	ed to be true at the time	of testing,				
Test gauge used: M	lake / Model Mid West	845 SN: 092	231317 Calibra	tion Date:3/14/2024		
Firm Name Safewa	ater Backflow	Certified Tester: Brad Weyant				
Firm Address PO Box 4002 Austin, TX 78765 Cert. Tester No: BP0016935						
Firm Phone # 512	-605-9790					

- TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS