City of Kyle - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping *purposes:

City of Kyle		**PWS ID:**	1050002
520 E RR 150		**Contact Name:**	Mickal Morrison
Kyle, Texas 78640		**Phone Number:**	737-877-2927

BPAT Information

Company Name:	Safewater Backflow and Irrigation	**Phone Number:**	5126059790
Tester Name:	Brad Weyant	**Email Address:**	brad@safewateratx.com
Address:	609 E 50TH	**License Number:**	BP0016935
	AUSTIN, Texas 78751	**License Expiration:**	12/3/2024

Location Information	Contact Information

Property Type:	Residential	**Company Name:**	
Business Name:		**Contact Name:**	
Property Address:	442 Wood Thrush Run	**Mailing Address:**	442 Wood Thrush Run
	Kyle, TX 78640		Kyle, TX 78640
		Phone Number:	
		Email Address:	

Backflow Information

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

Backflow Method:	Double Check Valve					
Main Assembly Manufacturer:	Apollo	**Model:**	DC4A	**Size:** 1	**Serial Number:**	97849C
Location:	Left front yard 5 feet from meter					
Hazard Type **:**	Irrigation - Non Chemical					

Backflow Test Information

Test Result:	Passed
Reason for Test:	New Installation

Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes

Is the assembly installed on a non-potable water supply (auxiliary)? No

Differential pressure gauge used:	MidWest 845-5 (potable)	**Serial Number:**	09231317	**Date Tested for Accuracy:**	3/14/2024

	Double Check Valve	
	Check Valve #1	**Check Valve #2**
Initial Test Date: 11/1/2024 Time: 9:00 AM	Held at 2.2 PSID ☑ ClosedTight ☐ Leaked	Held at 1.9 PSID ☑ ClosedTight ☐ Leaked
Repairs and Materials Used		
Repair Details		
Test After Repairs	Held at 0 PSID ☐ Closed Tight	Held at 0 PSID ☐ Closed Tight

Remarks