## City of Kyle - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping \*purposes:

City of Kyle 1050002 520 E RR 150 **Contact Name:** Mickal Morrison Kyle, Texas 78640 Phone Number: 737-877-2927

**BPAT Information** 

**Company Name:** Safewater Backflow and Irrigation

**Brad Weyant Tester Name:** Address: 609 E 50TH

AUSTIN, Texas 78751

Phone Number: **Email Address:** 

5126059790 brad@safewateratx.com

License Number: BP0016935

12/3/2024

License Expiration:

**Contact Information** 

**Property Type:** 

**Business Name: Property Address:**  Residential

471 Wood Thrush Run

Kyle, TX 78640

**Company Name:** Contact Name:

**Mailing Address:** 

471 Wood Thrush Run

Kyle, TX 78640

Phone Number:

**Email Address:** 

Size: 1

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

**Backflow Method: Double Check Valve** 

Main Assembly Manufacturer: Apollo Model: DC4A

Location: Right front yard 5 feet from meter Hazard Type \*\*\*\*: Irrigation - Non Chemical

**Test Result:** Passed New Installation Reason for Test:

Is the assembly installed in accordance with manufacturers recommendations and/or local codes? Yes

Is the assembly installed on a non-potable water supply (auxiliary)? No

Differential pressure

gauge used:

MidWest 845-5 (potable) Serial Number: 09231317

**Date Tested for Accuracy:** 

Serial Number: 88577C

3/14/2024

	Double Check Valve	
	Check Valve #1	Check Valve #2
Initial Test	Held at 1.9 PSID	Held at 2 PSID
Date: 7/3/2024	✓ ClosedTight	✓ ClosedTight
Time: 4:45 PM	Leaked	Leaked
Repairs and Materials Used		
Repair Details		
Test After Repairs	Held at 0 PSID	Held at 0 PSID
	Closed Tight	Closed Tight

Remarks

<sup>\*\*</sup> USE ONLY MANUFACTURER'S REPLACEMENT PARTS