Texas Commission on Environmental Quality BACKFLOW PREVENTION ASSEMBLY TEST AND MAINTENANCE REPORT

				ach assembly tested. A signed and dated original must be submitted to the public water supplier for recordkeeping *purposes:										
NAME OF PWS:				Round Rock Water										
PWS ID#:				260003										
PWS MAILING ADDRESS:				3400 Sunrise Rd Round Rock, TX 78665										
PWS CONTACT PERSON: ADDRESS OF SERVICE:				Inspections 4909 Fiore Trail Round Rock, TX 78665										
				bly detailed below has been tested and maintained as required by commission regulations										
	· ·		e operating v	•			u mainta	uneu as re	equiled by con	111115510) 1	eguia	uons	
and is	certifica						ON AS	SEMBLY	V (BPA).					
	Reduced	Pres		PE OF BACKFLOW PREVENTION ASSEMBLY (BPA): ple (RPBA) Reduced Pressure Principle-Detector (RPBA-D) Image: Content of the second sec							Τv	pe II		
Double Check Valve (D										-	ype II			
Pressure Vacuum Break				-		Spill-Resistant Pressure Vacuum Breaker (SVB)								
Manufacturer: Main: Apollo Bypass: Size: Main 1" Bypass:														
		Main: Apollo					Size:		Main 1"		Bypass:			
Model Number: Serial Number:					Bypass		BPA Location		Right front yard 5 feet from m			om me	eter	
Serial	Number:	Main 85465C			Bypas	SS:	BPA Serves:		Irrigation					
Reason for test: New X □ Existing □ Replacement ⊠ Old Model/Serial #														
Is the a	assembly	insta	lled in accord	dance with 1	nanufa	acturer recomm	endations and/or l		local codes?	×Υ	Yes 🗆 No		No	
Is the assembly installed on a non-potable wat						supply (auxiliary)?				ΠY	es	۸N	No	
TEST RESULT							Type II Assembly		PVB & SVB					
		Reduced Pressure Principle Asser				nbly (RPBA)								
PASS ⊠ FAIL □		DCVA												
		1 st Check 2 nd Check**			k***	Relief Valve	Bypass Check		Air Inlet	Ch	eck V	alve		
Initial Test Date: 6/6/2024 Time: 3:00PM		Held at2.2 Held at _2.3			3 psid	Opened at	_		Opened at psid		Held at			
		psid Closed Tig			-	psid			-		sid			
		Clos	ed Tight 🛛	Leaked		Did not	Leaked		Did it fully open Le			ed		
		Leaked		Louitou	_	open 📙			(Yes 🛛 /No 🗖])				
Repairs	sand	Mai	Main:											
Materia		Iviai												
Used**		Bypass:												
Test Af	fter		l at psid	Held at	neid	Opened at	Held at _	nsid	Opened at	nsid I	لماما	at		
<u>Test After</u> <u>Repair</u> Date:					I	· · · · · · · · · · · · · · · · · · ·	Closed		Opened at psid		psid			
		Closed Tight Closed T				I	Tight			r	pold			
Time:														
*** 2 nd check: numeric reading required for DCVA only														
Differential pressure gauge used: Potable: Non-Potable:														
Make/Model:		Mid West 845			SN:	09231317			sted for accuracy:		3/14/2024			
Remarks:														
Remar	KS:													
Carrie	onv NI	. !	Coferret	Dool-flo		Liconard Tree	n Norra		Dec d W/	ont.				
Compa	any Name	e:	: Safewater Backflow			Licensed Tester Name Brad Weyant (Print/Type):								
Company Address: PO Box 4 78765			PO Box 40	02 Austin		Licensed Tester Name (Signature):								
				52 musuil,	111									
Comp	any Phone	e #:	512-605-9	790		BPAT License # BP0016935								
License Expiration Date: 12/3/2024														
			т	ha ahawa ia		ied to be true a			ing					

* TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC §290.46(B)] ** USE ONLY MANUFACTURER'S REPLACEMENT PARTS