## City of Georgetown - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping \*purposes:

	City of Georgetown PO Box 1430	PWS ID: Contact Name:	2460001 Water Regulatory	
	Georgetown, Texas 78626	Phone Number:	512-930-3640	
		BPAT Information		
Company Name: Tester Name: Address:	Safewater Backflow and Irrigation Brad Weyant 609 E 50TH AUSTIN, Texas 78751	Phone Number: Email Address: License Number License Expirati		
	Location Information		Contact Information	
Property Type: Business Name: Property Address:	Residential 5837 Sean Paul Ln Georgetown, TX 78641	Company Name: Contact Name: Mailing Address Phone Number: Email Address:		
		Backflow Information		
The backflow prevention acceptable parameters.	assembly detailed below has been tes	sted and maintained as required by com	mission regulations and is certified to be operating within	
Backflow Method: Main Assembly Manufa Location: Hazard Type ****:	Double Check Valve acturer: Apollo I Right front yard 5 feet from meter Irrigation - Non Chemical	Model: DC4A Size: 7	1 Serial Number: 88667C	
		Backflow Test Information		
Fest Result: Reason for Test: s the assembly installe	Passed New Installation ed in accordance with manufacturer	s recommendations and/or local code	es? Yes	
s the assembly installe	ed on a non-potable water supply (a	uxiliary)? No		
Differential pressure auge used:	MidWest 845-5 (potable)	Serial Number: 09231317	Date Tested for Accuracy: 3/14/2024	
	Doub	le Check Valve		
	Check Valve #1	Check Valve #2		
Initial Test Date: 8/14/2024 Time: 10:55 AM	Held at 2.1 PSID	Held at 1.9 PSID ClosedTight Leaked		
Repairs and Materials Used				
Repair Details				
Test After Repai	rs Held at 0 PSID	Held at 0 PSID		
		Remarks		

The above is certified to be true at the time of testing. \* TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC 290.46(B)] \*\* USE ONLY MANUFACTURER'S REPLACEMENT PARTS \*\*\* 2nd Check: Numeric reading required for double check valve only. \*\*\*\* Indicates additional information not present on the standard TCEQ report