

## Travis County WC&ID #10 - Backflow Prevention Assembly Test and Maintenance Report

The following form must be completed for each assembly tested for recordkeeping \*purposes:

Travis County WC&ID #10  
5324 Bee Cave Road  
Austin, Texas 78746

**PWS ID:** 2270182  
**Contact Name:** Carla Orts  
**Phone Number:** (512) 327-2230

### BPAT Information

**Company Name:** Safewater Backflow and Irrigation  
**Tester Name:** Brad Weyant  
**Address:** 609 E 50TH  
AUSTIN, Texas 78751

**Phone Number:** 5126059790  
**Email Address:** brad@safewateratx.com  
**License Number:** BP0016935  
**License Expiration:** 12/3/2027

### Location Information

**Property Type:** Residential  
**Business Name:**  
**Property Address:** 6102 Forest Hills Dr  
Austin, TX 78746

### Contact Information

**Company Name:**  
**Contact Name:**  
**Mailing Address:** 6102 Forest Hills Dr  
Austin, TX 78746  
**Phone Number:**  
**Email Address:**

### Backflow Information

The backflow prevention assembly detailed below has been tested and maintained as required by commission regulations and is certified to be operating within acceptable parameters.

**Backflow Method:** Reduced Pressure Principle  
**Main Assembly Manufacturer:** Febco **Model:** 860 **Size:** 1 **Serial Number:** HA23544  
**Location:** Right front yard along fence, 20 feet from meter  
**Hazard Type \*\*\*\*:** Irrigation - Non Chemical

### Backflow Test Information

**Test Result:** Passed  
**Reason for Test:** New Installation

**Is the assembly installed in accordance with manufacturers recommendations and/or local codes?** Yes

**Is the assembly installed on a non-potable water supply (auxiliary)?** No

**Differential pressure gauge used:** MidWest 845-5 (potable) **Serial Number:** 09231317 **Date Tested for Accuracy:** 3/14/2024

	Reduced Pressure Principle		
	Check Valve #1	Check Valve #2	Relief Valve
<b>Initial Test</b> Date: 12/2/2024 Time: 1:35 PM	Held at 7.7 PSID <input checked="" type="checkbox"/> ClosedTight <input type="checkbox"/> Leaked	Held at __ PSID <input checked="" type="checkbox"/> ClosedTight <input type="checkbox"/> Leaked	Opened at 3.8 PSID <input type="checkbox"/> Did not open
<b>Repairs and Materials Used</b>			
<b>Repair Details</b>			
<b>Test After Repairs</b>	Held at 0 PSID <input type="checkbox"/> Closed Tight	Held at __ PSID <input type="checkbox"/> Closed Tight	Opened at 0 PSID

### Remarks

The above is certified to be true at the time of testing.

\* TEST RECORDS MUST BE KEPT FOR AT LEAST THREE YEARS [30 TAC 290.46(B)]

\*\* USE ONLY MANUFACTURER'S REPLACEMENT PARTS

\*\*\* 2nd Check: Numeric reading required for double check valve only.

\*\*\*\* Indicates additional information not present on the standard TCEQ report