Backflow Prevention Assembly Test Details

Special Services Division

3907 South Industrial DR

Austin, TX 78744-1070



Test and Maintenance Report

Water System ID# 2270001

Phone: (512) 972-1060 FAX: (512) 972-1260



*** Test records must be kept by the customer for at least three years ***

	*** Test records must	pe kept by the customer for at least three years ***		
	Backf	ow Assembly Information		
Serial Number:	97671C	Manufacturer:	APOLLO/CONBRACO	
Model:	DC4A	Size:	1	
Service Address:		6406 COWMAN WAY 78747		
Assembly location on the property:		FRONT LEFT - CORNER OF HOME 10' FROM THE METER		
Reason the assembly is installed:		IRRIGATION W/ CITY POTABLE WATER		
Is this assembly installed to code requirements?		Yes		
	C	ustomer Information		
Property Owner / Agent:		EMPIRE HOMES		
Mailing Address:	iling Address:		6406 COWMAN WAY	
City / State / Zip:		AUSTIN, TX 78747	AUSTIN, TX 78747	
Phone:				
		Backflow Test		
		DCVA		
Initial Test	С	heck Valve #1	Check Valve #2	
		2.1 PSID	2.1 PSID	
Repairs				
Test After Repairs				
Test Date:		Aug 9, 2024		
Backflow Test Status:		Passed		
		Tester Information		
The backflow technician listed below	v has previously certifie	d that the information on this report was	true and correct on the date of this test.	
Backflow Technician:		STEVENSON, SCOTT		
License:		BP0017507		