



Test and Maintenance Report

Water System ID# 2270001

Special Services Division
3907 South Industrial DR
Austin, TX 78744-1070

Phone: (512) 972-1060
FAX: (512) 972-1260



*** Test records must be kept by the customer for at least three years ***

Backflow Assembly Information

| | | | |
|---|-----------------------------------|----------------------|-----------------|
| Serial Number: | 85516C | Manufacturer: | APOLLO/CONBRACO |
| Model: | DC4A | Size: | 1 |
| Service Address: | 8520 PICNIC HOUSE PATH 78744 | | |
| Assembly location on the property: | LEFT FRONT YARD 5 FEET FROM METER | | |
| Reason the assembly is installed: | IRRIGATION W/ CITY POTABLE WATER | | |
| Is this assembly installed to code requirements? | Yes | | |

Customer Information

| | |
|--------------------------------|------------------------------|
| Property Owner / Agent: | TAYLOR MORRISON OF TEXAS INC |
| Mailing Address: | |
| City / State / Zip: | |
| Phone: | |

Backflow Test

| Initial Test | DCVA | |
|------------------------------|----------------|----------------|
| | Check Valve #1 | Check Valve #2 |
| | 2.2 PSID | 2 PSID |
| Repairs | | |
| Test After Repairs | | |
| Test Date: | May 31, 2024 | |
| Backflow Test Status: | Passed | |

Tester Information

The backflow technician listed below has previously certified that the information on this report was true and correct on the date of this test.

| | |
|-----------------------------|-----------------|
| Backflow Technician: | WEYANT, BRADLEY |
| License: | BP0016935 |
| Gauge Serial Number: | 09231317 |